

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/PWDDt. 23-01-1970)

	Name of the Officer	REKHA M	
2	Name of the School	RIMS INTERNATIONAL SCHOOL	
3	Location with name of Education District/Sub.District	VARAMKADAVU KANNUR DIST.	
4	Classification of Building as specified in column 4 of the Application for fitness certificate and size		
		1 st Partial Occupancy	2 nd Partial Occupancy
	Basement		931.37 M2
	Ground Floor	868.07 M2	971.37 M2
	First Floor	863.42 M2	1127.65 M2
	Second Floor	823.52 M2	1126.65 M2
	Plinth Area	2555.01 M2	4157.10 M2
5	Period for which the certificate is issued		
6	Nature of defects if any	NIL	
a	Foundation and basement		
b	Superstructure	RCC framed structure	
c	Doors and Windows	Irool Door & Aluminium Window	
d	Wood work wrought and put up	No	
e	Roof	RCC	
f	Flooring	Tile	
g	Miscellaneous (Cracks, etc.)		
7	Any major defects noticed which will render the Building unsafe in any manner	No	
8	Whether maintenance works have been done properly	Yes	
9	Whether structure is sound or not to conducting classes	Yes, sound for conducting classes under normal wind weather condition	

Note: 1. The stability of the structures should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 20/05/2024..... and found to be fit/unfit to conduct classes, for the period 01/06/2024 to 31/03/2025..... for the reasons stated above.

Place: ...Chelora.....

Date: ...28/05/2024.....




 Assistant Engineer
 LSGD
 CHELORA MUNICIPAL CORPORATION
 CHELORA, KANNUR DISTRICT
 Assistant Engineer